


ECGR 4161 →

6/14/11

(1)

## Lab 2 → Lessons Learned

- \* If it does not work, wait 30 seconds try again.
- \* Issue loading vi? Try creating a new project/vi.
- \* Ethernet sometime stopped working
- \* Pin 3 on, all others off, hit reset, then Resets the IP address
- \* What is the Model → Sharp IR Sensor



\* Compact RIO pinout → NI site

---

Hint → Lab 3 → Test Sensor first

Due June 21  
 Homework 3 → 1 powerpoint & 30 second video (2)

ECGR 4161 6/14/11

Stelvik	→	Automobile manufacturing <del>30 second video</del>
Harris	→	3 access printer
McLean	→	Pack bot - ish
Zapata	→	UAV (unmanned Aerial Vehicle)
Haw ayeek	→	Rescue mission
Bosinala	→	Surgical
Bou Sabon	→	Electronics assembly
Pavlich	→	Inspection
Fridlyand	→	entertainment (humanoid)
Pruss	→	rough lumber vehicle
Barfield	→	
Pisani	→	